

# **2022 ANNUAL DAM AND DIKE INSPECTION REPORT**

**CCR ASH PONDS**

**WELSH POWER PLANT  
CASON, TEXAS**

**December 2022**

**Prepared by: American Electric Power Service Corporation  
1 Riverside Plaza  
Columbus, OH 43215**



**GERS-22-043**

# 2022 Annual Dam & Dike Inspection Report

## CCR Ash Ponds

DOCUMENT ID: GERS-22-043  
Revision 0


**WELSH POWER PLANT  
CASON, TEXAS**

**INSPECTION DATE November 3, 2022**

**PREPARED BY:** Brett A Dreger **DATE** 12/19/2022  
Brett A. Dreger, P.E.

**REVIEWED BY:** [Signature] **DATE** 12-19-2022  
Shah S. Baig, P.E.

**APPROVED BY:** Gary F. Zych **DATE** 12/20/2022  
Gary F. Zych, P.E.  
Manager - AEPSC Geotechnical Engineering  
AEPSC Registered Firm No. F-3341



**PROFESSIONAL ENGINEER  
SEAL & SIGNATURE**

I certify to the best of my knowledge, information, and belief the information contained in this report meets the requirements of 40 CFR § 257.83(b).

## TABLE OF CONTENTS

<b>1.0</b>	<b>INTRODUCTION.....</b>	<b>1</b>
<b>2.0</b>	<b>DESCRIPTION OF IMPOUNDMENTS.....</b>	<b>1</b>
<b>2.1</b>	<b>PRIMARY BOTTOM ASH POND .....</b>	<b>1</b>
<b>2.2</b>	<b>BOTTOM ASH STORAGE POND.....</b>	<b>2</b>
<b>3.0</b>	<b>REVIEW OF AVAILABLE INFORMATION (257.83(B)(1)(I)) .....</b>	<b>3</b>
<b>4.0</b>	<b>CHANGES IN GEOMETRY SINCE LAST INSPECTION (257.83(B)(2)(I)) .....</b>	<b>3</b>
<b>5.0</b>	<b>CHANGES THAT EFFECT STABILITY OR OPERATION (257.83(B)(2)(VII)) ...</b>	<b>3</b>
<b>6.0</b>	<b>IMPOUNDMENT CHARACTERISTICS (257.83(B)(2)(III, IV, V)) .....</b>	<b>4</b>
<b>6.1</b>	<b>PRIMARY BOTTOM ASH POND .....</b>	<b>4</b>
<b>6.2</b>	<b>BOTTOM ASH STORAGE POND.....</b>	<b>4</b>
<b>7.0</b>	<b>INSPECTION (257.83(B)(1)(II)) .....</b>	<b>5</b>
<b>7.1</b>	<b>GENERAL .....</b>	<b>5</b>
<b>7.2</b>	<b>VISUAL INSPECTION (257.83(b)(2)(i)).....</b>	<b>7</b>
<b>7.3</b>	<b>INSTRUMENTATION (257.83(b)(2)(ii)) .....</b>	<b>9</b>
<b>8.0</b>	<b>SUMMARY OF FINDINGS .....</b>	<b>9</b>
<b>9.0</b>	<b>RECOMMENDATIONS.....</b>	<b>10</b>
<b>9.1</b>	<b>MAINTENANCE ITEMS .....</b>	<b>11</b>
<b>9.2</b>	<b>ITEMS TO MONITOR.....</b>	<b>11</b>
<b>9.3</b>	<b>DEFICIENCIES (257.83(b)(2)(vi)).....</b>	<b>11</b>

## LIST OF TABLES

Table 1 Summary of Relevant Storage Information for Primary Bottom Ash Pond

Table 2 Summary of Relevant Storage Information for Bottom Ash Storage Pond

## APPENDICES

### Appendix A

Figure 1 - Vicinity Map

Figure 2 - CCR Pond Complex General Layout

### Appendix B

Figure 3A – Photograph Location Map, Primary Bottom Ash Pond

Photographs of Primary Bottom Ash Pond

### Appendix C

Figure 3B – Photograph Location Map, Bottom Ash Storage Pond

Photographs of Bottom Ash Storage Pond

### Appendix D

Figure 4A - Piezometers Location Map

Figure 4B - Primary Bottom Ash Pond Piezometer Data

## **1.0 INTRODUCTION**

This report was prepared by AEP- Geotechnical Engineering Services (GES) section, in part, to fulfill requirements of 30 TAC 352.831 (40 CFR 257.83) and to provide Southwestern Electric Power Company (SWEPCO) and Welsh Power Plant with an evaluation of the facility.

The AEP J. Robert Welsh Plant is located in southern Titus County, approximately 8 miles northeast of Pittsburg, Texas, and approximately two miles northwest of Cason, Texas. Figure 1 shows the plant inspection vicinity map. The Ash ponds at the Welsh Plant include the Primary Bottom Ash Pond and the Bottom Ash Storage Pond. The Primary Bottom Ash Pond CCR unit is located southwest of the Plant and directly west of the Welsh Reservoir. The Bottom Ash Storage Pond CCR unit is located at the south end of the Plant and approximately 1,000 feet west of the Welsh Reservoir. Figure 2 shows the two Ash Ponds general layout.

Mr. Brett A. Dreger, P.E., from the Geotechnical Engineering Services Section, conducted the Ash Ponds Inspection. Mr. Greg Carter, P.E. Regional Engineering for Welsh Plant was the facility contact for the inspection and participated during the inspection. The inspection was performed on November 3, 2022. Weather conditions were mostly sunny, with temperatures ranging from 49° F in the morning to low 70's° F in the afternoon.

This report has been prepared by Mr. Brett A. Dreger, P.E., under the direct supervision of Mr. Gary Zych, P.E., AEP's Geotechnical section manager. The report presents: Description of the impoundments, Summary of Visual Observations; Conclusions; and Recommendations. Photographs identifying typical conditions of area findings, items that need correction or requiring additional monitoring, have been selected from the inspection field photographic file and provided in the Appendices B and C of this report.

## **2.0 DESCRIPTION OF IMPOUNDMENTS**

### **2.1 PRIMARY BOTTOM ASH POND**

The Primary Bottom Ash Pond was placed into operation in 1977 and is located in a topographically low area that had been an unnamed intermittent tributary of Swauano Creek prior

to development of the Site. The Primary Bottom Ash Pond is bounded by natural ground surface (topographically higher areas) to the north and west, and embankment dikes to the south and east. The elevation at the top of embankment along the crest area is approximately 340.0 feet above msl and the toe elevation of the embankment is approximately 300.0 feet above msl. The Primary Bottom Ash Pond embankment is approximately 40 feet in height. The downstream slope of the Primary Bottom Ash Pond embankment is inundated by the cooling lake reservoir (Normal Lake Level is 320.0 feet above msl). These dikes are predominantly constructed of compacted sandy clay and clayey sand. The embankment dike south of the Primary Bottom Ash Pond includes a drainage canal that receives overflow (clear) water from the Primary Bottom Ash Pond. The water level in the Primary Bottom Ash Pond is controlled by a weir box which discharges into the drainage canal. The primary emergency spillway, which consists of a concrete weir set within an earthen channel that discharges into the drainage canal; the primary emergency spillway is approximately 950 feet to the west of the embankment. The clear water in the drainage canal flows east and discharges into the clear water pond. The secondary emergency spillway is located at the right end of the embankment and discharges directly into the Clearwater Pond. Dimensions of the secondary emergency spillway are a 30-foot bottom width at crest elevation 335 feet msl with 10H:1V side slopes, for a total width of 130 feet and depth of 5 feet. Flows through the secondary emergency spillway would discharge directly into the Clearwater Pond. The storage capacity of the Primary Bottom Ash Pond at elevation 334 feet above msl is approximately 319.22 acre-ft.

## **2.2 BOTTOM ASH STORAGE POND**

The Bottom Ash Storage Pond (Winston Pond) was placed into operation in 2000 and is located in a topographically high area of the Plant. The Bottom Ash Storage Pond embankments are approximately 20 feet in height and are constructed of compacted clay on a 3:1 slope (3 feet horizontal, 1 foot vertical). The elevation at the base of the embankment is approximately 340 feet above msl, and the elevation at the top of the embankment around the perimeter of the Bottom Ash Storage Pond is approximately 360 feet above msl.

The Bottom Ash Storage Pond is approximately 22 acres in size. The principal spillway for the Bottom Ash Storage Pond is located near the southeast corner of the pond and consists primarily

of an 18-inch pipe drain at elevation 350.5 feet above msl and also of a 40-foot-long broad-crested weir with a crest elevation of 355 feet above msl. The emergency spillway is an 8-foot-wide weir with a rock rip-rap discharge chute located along the southern embankment at an elevation of 358 feet above msl. The storage capacity of the Bottom Ash Storage Pond at elevation 358 feet above msl is approximately 344 acre-ft.

### **3.0 REVIEW OF AVAILABLE INFORMATION (257.83(b)(1)(i))**

A review of available information regarding the status and condition of the CCR Ponds, which include files available in the CCR operating record, such as design and construction information, periodic structural stability assessments, previous 7-day inspection reports, 30-day instrumentation data, and previous annual inspections has been conducted. Based on the review of the data there were no signs of actual or potential structural weakness or adverse conditions.

### **4.0 CHANGES IN GEOMETRY SINCE LAST INSPECTION (257.83(b)(2)(i))**

No modifications have been made to the geometry of the Primary Bottom Ash Pond and the Bottom Ash Storage Pond since the last annual inspection. The geometry of the impoundment has remained essentially unchanged.

### **5.0 CHANGES THAT EFFECT STABILITY OR OPERATION (257.83(b)(2)(vii))**

Based on interviews with plant personnel and field observations there were no changes to the Primary Bottom Ash Pond since the last annual inspection that would affect the stability or operation of the impounding structure.

In April of 2021, the Bottom Ash Storage Pond ceased operations and no longer receives any CCR transport waters or CCR materials into the pond. Bottom Ash Storage Pond also stopped receiving all storm water runoff from the landfill and surrounding areas. These operational changes would not be expected to affect the stability of the impounding structure.

## 6.0 IMPOUNDMENT CHARACTERISTICS (257.83(b)(2)(iii, iv, v))

### 6.1 PRIMARY BOTTOM ASH POND

Table 1 is a summary of the minimum, maximum, and present depth, and elevation of the impounded water since the previous annual inspection; the storage capacity of the impounding structure at the time of the inspection; and the approximate volume of the impounded water at the time of the inspection.

**Table 1 - Summary of Relevant Storage Information for Primary Bottom Ash Pond**

	<b>Primary Bottom Ash Pond</b>
Approximate <b>Minimum</b> depth of impounded water since last annual inspection	30.0 ft (330.0 ft)
Approximate <b>Maximum</b> depth of impounded water since last annual inspection	32.9 ft (332.90 ft)
Approximate <b>Present</b> depth of impounded water at the time of the inspection	30.8 ft (330.8 ft)
Approximate <b>Minimum</b> depth of CCR since last annual inspection	10.0 ft (310.0 ft)
Approximate <b>Maximum</b> depth of CCR since last annual inspection	32.5 ft (332.50 ft)
Approximate <b>Present</b> depth of CCR at the time of the inspection	32.5 ft (332.50 ft)
Storage Capacity of impounding structure at the time of the inspection	319.22 acre-ft
Approximate volume of impounded water at the time of the inspection	106.22 acre-ft
Approximate volume of CCR at the time of the inspection	213 acre-ft

### 6.2 BOTTOM ASH STORAGE POND

Table 2 is a summary of the minimum, maximum, and present depth, and elevation of the impounded water since the previous annual inspection; the storage capacity of the impounding structure at the time of the inspection; and the approximate volume of the impounded water at the time of the inspection.

**Table 2 - Summary of Relevant Storage Information for Bottom Ash Storage Pond**

	<b>Bottom Ash Storage Pond</b>
Approximate <b>Minimum</b> depth of impounded water since last annual inspection	0.0 ft (340.0 ft)
Approximate <b>Maximum</b> depth of impounded water since last annual inspection	10.8 ft (350.8 ft)
Approximate <b>Present</b> depth of impounded water at the time of the inspection	0.0 ft (340.0 ft)
Approximate <b>Minimum</b> depth of CCR since last annual inspection	0.0 ft (340.0 ft)
Approximate <b>Maximum</b> depth of CCR since last annual inspection	18.0 ft (358.0 ft)
Approximate <b>Present</b> depth of CCR at the time of the inspection	18.0 ft (358.0 ft)
Storage Capacity of impounding structure at the time of the inspection	344 acre-ft
Approximate volume of impounded water at the time of the inspection	0 acre-ft
Approximate volume of CCR at the time of the inspection	261 acre-ft

**7.0 INSPECTION (257.83(b)(1)(ii))**

**7.1 GENERAL**

The summary of the visual observations uses terms to describe the general appearance or condition of an observed item, activity, or structure. Their meaning is understood as follows:

Good: A condition or activity that is generally better or slightly better than what is minimally expected or anticipated from a design or maintenance point of view.

Fair or Satisfactory: A condition or activity that generally meets what is minimally expected or anticipated from a design or maintenance point of view.

Poor: A condition or activity that is generally below what is minimally expected or anticipated from a design or maintenance point of view.



- Minor: A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance condition is below what is normal or desired, but which is not currently causing concern from a structure safety or stability point of view.
- Significant: A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance program has neglected to improve the condition. Usually, conditions that have been previously identified in the previous inspections but have not yet been corrected.
- Excessive: A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance condition is below or worse than what is normal or desired, and which may have affected the ability of the observer to properly evaluate the structure or area being observed or which may be a concern from a structure safety or stability point of view.

In addition, a “deficiency” is some evidence that a dam/dike has developed a problem that could impact the structural integrity of the dam/dike. There are four general categories of deficiencies. These four categories are described below:

#### 1. Uncontrolled Seepage

Uncontrolled seepage is seepage that is not behaving as the design engineer has intended. An example of uncontrolled seepage is seepage that comes through or around the embankment and is not picked up and safely carried off by a drain. Seepage that is collected by a drain can still be uncontrolled if it is not safely collected and transported, such as seepage that is not clear. Seepage that is unable to be measured and/or observe it is considered uncontrolled seepage.

[Wet or soft areas are not considered as uncontrolled seepage but can lead to this type of deficiency. These areas should be monitored frequently]

#### 2. Displacement:

Displacement of the embankment is large scale movement of part of the dam/dike. Common signs of displacement are cracks, scraps, bulges, depressions, sinkholes, and slides.

3. Blockage of Control Features:

Blockage of Control Features is the restriction of flow at spillways, decant or pipe spillways, or drains.

4. Erosion:

Erosion is the gradual movement of surface material by water, wind, or ice. Erosion is considered a deficiency when it is more than a minor routine maintenance item.

## **7.2 VISUAL INSPECTION (257.83(b)(2)(i))**

A visual inspection of the CCR Ponds was conducted to identify any signs of distress or malfunction of the impoundment and appurtenant structures. Specific items inspected included all structural elements of the dam such as upstream and downstream slopes, crest, and toe. Photograph's location map and inspection photographs are included in Appendices B and C.

### **7.2.1 PRIMARY BOTTOM ASH POND**

- (i) Typical condition of the upstream slope, crest, and downstream slope is illustrated in Photographs No. 1-4. The dike appeared in satisfactory and stable condition. There were no signs of settlement, misalignment, sloughing or erosion. Slightly overgrown vegetation was noticed along the upstream slope and on the downstream slope near the rock rip rap. There was some significant damage of the downstream slope near the crest from hog rutting activities (Photograph No. 3)
- (ii) The two ash discharge pipes and ash sluice location are located at the northeast corner of the pond. Other effluent from the plant is discharge at the north dike. All the sluice pipes and base support did not indicate any sign of misalignment, settlement, or deterioration. Overall, the discharge pipes appeared in good functional condition.
- (iii) Photograph No. 5 illustrates the primary emergency spillway located towards the southeast section of the south dike. The primary emergency spillway appeared to be in satisfactory condition but was covered with overgrown vegetation preventing a full inspection of the area. The secondary emergency spill way was in satisfactory condition an showed no signs

of erosion, misalignment, deterioration, or misplaced rip rap material.

- (iv) A canal is located at the south end of the pond. A typical view of the discharge canal concrete weir box is illustrated in Photograph No. 6. The canal conveys water from southwest corner of the ash pond to the Clearwater Pond located at the west southeast end. The canal indicated positive drainage condition. Excessive vegetation was noticed along the banks of the canal.

### **7.2.2 BOTTOM ASH STORAGE POND**

- (i) The east portion of the downstream slope is illustrated in Photographs No. 7 and 8. Slightly overgrown vegetation was noticed on these slopes. The slope appeared in satisfactory and stable condition with no signs of settlement, misalignment, sloughing or erosion.
- (ii) Photographs No. 9 and 10 illustrate the south downstream slope areas. The slopes appeared in satisfactory and stable condition with some minor overgrown vegetation. There were no signs of settlement, misalignment, sloughing or erosion.
- (iii) The northwest section of the west dike downstream slope is illustrated in Photograph No. 11. The slope appeared in satisfactory and stable condition with slightly overgrown vegetation preventing a full inspection of the slopes. There were no signs of settlement, misalignment, sloughing or erosion.
- (iv) Photograph No. 12 illustrates the emergency spillway location at the southwest section of the south dike. The spillway riprap was in satisfactory condition with some vegetation near the edges of the rock rip rap.
- (v) Photographs No. 13 and 14 illustrate the interior conditions, upstream slope, and crest areas of the pond. The upstream slope appeared to be in good and stable condition and mostly buttress with ash. The geosynthetic liner appeared intact and in good condition. The crest appeared in good and stable condition. Overgrown vegetation was noticed throughout the interior of the pond and on the crest area.

- (vi) A small area within the pond is used as a control weir with a principal spillway inlet and outlet pipe located in southeast corner (Photograph No. 15). The principal spillway basin was dry at the time of inspection with no flow through the inlet or outlet pipes. The basin is silted up with ash sediment to the flow line of the inlet and outlet pipes and could possibly restrict flows when passing water from the main pond through the basin to the outlet pipe.
- (vii) There are two pipe culverts located at the northwest corner of the pond that used to convey storm water from the landfill and surrounding areas into the pond. The storm water runoff channel and inlet pipes have been plugged to prevent storm water runoff from entering the pond (No Photograph was Taken).

### **7.3 INSTRUMENTATION (257.83(b)(2)(ii))**

The monitoring instrumentation for the Primary Bottom Ash Pond consists of the one (1) active piezometer (B-2) located through the main embankment area. There is no monitoring instrumentation for the Bottom Ash Storage Pond (Winston Pond). The location of the instrumentation is shown in Attachment D, Figure 4A. The maximum and minimum readings of Piezometer B-2 since the last annual inspection, a time of October 2021 to November 2022, were 323.57 ft msl and 321.77 ft msl, respectively. Piezometer B-2 levels appeared consistent from month to month and reacted to the fluctuation in tail water levels (i.e., main lake). The results of the measurements of the piezometer are shown in Appendix D, Figure 4B.

### **8.0 SUMMARY OF FINDINGS**

Based on the visual observations and the inspection of the facilities, the dam and appurtenances are generally in satisfactory condition. Specific conclusions related to this inspection is included as follows.

#### Primary Bottom Ash Pond:

- There is no evidence of distress that would indicate the possibility of immediate sliding, slope instability, settlement, misalignment or cracking of the ash pond embankments. As such it is concluded that the dam and dikes are performing as designed.

- There was significant hog rutting damage on the downstream slope of the Primary Bottom Ash Pond.
- Overgrown vegetation was noticed throughout the pond areas and should be maintained accordingly.

Bottom Ash Storage (Winston) Pond:

- There is no evidence of distress that would indicate the possibility of immediate sliding, slope instability, settlement, misalignment or cracking of the bottom ash pond embankments. As such it is concluded that the dam and dikes are performing as designed.
- Vegetation management for the facilities is considered satisfactory. However, some areas are overgrown and should be maintained accordingly.
- The principal spillway basin is silted up with ash sediment to the flow line of the inlet and outlet pipes and could possibly restrict flows when passing water from the main pond through the basin to the outlet pipe.

## **9.0 RECOMMENDATIONS**

A summary of our recommendations for general maintenance and continued monitoring, as well as any recommendations for remedial activities, is provided as follows:

- As noted, all the excessive vegetation should be cut down and maintained consistently to control and properly manage it.
- The damaged slope area from hog rutting activities on the downstream slope of the primary ash storage pond should be repaired and seeded.
- The sediment buildup in the principal spillway basin area of the bottom ash storage pond should be cleaned out to promote un-obstructive flows through the basin area to the outlet pipe.

## **9.1 MAINTENANCE ITEMS**

The following maintenance items were identified during the visual inspection:

- Vegetation management for the facilities is considered satisfactory. Some areas are overgrown and should be managed with controlled vegetation growth, however, there are a few areas that have sparse vegetation.

## **9.2 ITEMS TO MONITOR**

- No items to monitor

## **9.3 DEFICIENCIES (257.83(b)(2)(vi))**

There were no deficiencies or signs of structural weakness or disruptive conditions that were observed at the time of the inspection that would require additional investigation or remedial action. There were no deficiencies noted during any of the quarterly inspections. If any of these conditions occur before the next annual inspection, contact AEP Geotechnical Engineering immediately.



If you have any questions regarding this report, please contact Brett Dreger at Audinet: 200-2258 or Gary Zych at Audinet: 200-2917.

## Appendix A

Figure 1 - Vicinity Map

Figure 2 - CCR Pond Complex General Layout

File: Q:\AEP Dam Inspections\Welsh\Drawings\Swauano Ck dam\Swauano Creek Dam\WELSH LOCATION MAP.dwg Layout: Layout1 Plotted Apr 14, 2009 - 2:45pm



Source: Google Maps

<b>AEP WELSH POWER PLANT SWAUANO CREEK DAM TITUS COUNTY, TX</b>	
URS Corporation 9400 Amberglen Blvd. Austin, Texas 78729	
<b>DAM &amp; DIKE INSPECTION VICINITY MAP</b>	
DATE	4/14/2009
SCALE	1" = 4 MILES
URS JOB NUMBER	41009103
DRAWN BY	SLC

Figure 1 Plant Inspection Vicinity Map



# **FIGURE 2 - SITE LOCATION MAP**

## **WELSH POWER PLANT, CASON, TX**



## Appendix B

Figure 3A – Photograph Location Map, Primary Bottom Ash Pond  
Photographs of Primary Bottom Ash Pond



# FIGURE 3A - PHOTOGRAPH LOCATION MAP

PRIMARY BOTTOM ASH POND, WELSH POWER PLANT, CASON, TX








<p>Photo # 1</p>	 A photograph showing the upstream slope of the Primary Bottom Ash Pond. The foreground is dominated by tall, dry, brownish grasses. The pond's edge is visible, with water that appears slightly turbid. In the background, there is a line of trees and a clear blue sky with a few clouds.
<p>Photo # 2</p>	 A wide-angle photograph of the downstream slope of the Primary Bottom Ash Pond. The slope is covered in green grass, though there are some patches of bare earth or disturbed soil. The pond is visible on the left side of the frame. The background shows a line of trees and a clear blue sky.
<p>Photo # 3</p>	 A close-up photograph of the downstream slope of the Primary Bottom Ash Pond, showing significant disturbance. The ground is covered in dark, churned-up soil and dry, tangled vegetation, which is characteristic of hog activity. The slope rises towards the crest in the background, where a fence and some trees are visible under a clear sky.



Photo # 4

Typical crest area of Primary Bottom Ash Pond.



Photo # 5

Emergency spillway channel of Primary Bottom Ash Pond.



Photo # 6

View of the Primary Bottom Ash Pond discharge canal concrete weir box.



## Appendix C

Figure 3B – Photograph Location Map, Bottom Ash Storage Pond  
Photographs of Bottom Ash Storage Pond



# FIGURE 3B - PHOTOGRAPH LOCATION MAP

## BOTTOM ASH STORAGE POND, WELSH POWER PLANT, CASON, TX






Photo # 7

Bottom Ash Storage Pond (Winston Pond) looking at downstream slope conditions on east side.



Photo # 8

Bottom Ash Storage Pond (Winston Pond) looking at downstream slope conditions on southeast side.



Photo # 9

Bottom Ash Storage Pond (Winston Pond) Looking at downstream slope conditions on south side.





Photo # 10

Bottom Ash Storage Pond (Winston Pond) Looking at downstream slope conditions on southwest side.



Photo # 11

Bottom Ash Storage Pond (Winston Pond) looking at downstream slope conditions on west side.



Photo # 12

Bottom Ash Storage Pond (Winston Pond) downstream slope looking at emergency spillway channel.



Photo # 13

Bottom Ash Storage Pond (Winston Pond) looking at typical interior conditions.



Photo # 14

Bottom Ash Storage Pond (Winston Pond) looking at typical interior conditions.



Photo # 15

Bottom Ash Storage Pond (Winston Pond) interior area looking at principal spillway outlet pipe and control weir at southeast corner.



## Appendix D

Figure 4A - Piezometers Location Map


Figure 4B - Primary Bottom Ash Pond Piezometer Data




# FIGURE 4A - INSTRUMENT LOCATION MAP

## Primary Ash Pond

NORMAL 20  
LOW WATER  
AREA=1191'



200 0 200 400  
Graphic Scale



**ETTL**  
**ENGINEERS & CONSULTANTS**  
MAIN OFFICE  
1717 Edget Erwin  
Tyler, Texas 75702  
(903) 595-4421

**WELSH POWER PLANT**  
**PITTSBURGH, TEXAS**

**PLATE 1 - PLAN OF BORINGS**  
JOB NO.: G3242-095  
DATE: JAN. 2010  
SCALE: AS SHOWN

APPROVED BY:  
  
DRAWN BY:  
K.C.R.

Figure 4B - Primary Pond Piezometer Readings

