

Big Sandy Plant

Notice of Completion of Closure—February 28, 2020 Revision 1

Bottom Ash Pond

On January 29, 2020, the Big Sandy bottom ash pond CCR unit was transitioned to closure status in accordance with 40 CFR 257.102. All CCR materials were removed from the unit, including removal of at least two feet of the natural lean clay or sandy lean clay and silt soils beneath the unit to remove any CCR potentially mixed with soil, and none of the monitored groundwater parameters were found to exceed their corresponding groundwater protection standards.

This notice of completion of closure is being placed in the operating record in accordance with 40 CFR 257.102(h).

CLOSURE CERTIFICATION BY QUALIFIED PROFESSIONAL ENGINEER


I certify that the Big Sandy Plant Bottom Ash Pond (BAP) has been closed in accordance with the closure plan specified by paragraph 257.102(b) and the requirements of section 257.102.

DAVID ANTHONY MILLER

Printed Name of Licensed Professional Engineer

David Anthony Miller

Signature



33232

License Number

KENTUCKY

Licensing State

01.29.2020

Date

Appendix—Record of Changes

Revision 1—Added notice of completion of closure to closure certification